



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

March 07, 2013

Reviewed:

<b>Mine Name:</b> Barneys Canyon	<b>Permit Number:</b> M/035/0009
<b>Operator Name:</b> Barneys Canyon Mining Company	<b>Inspection Date:</b> May 09, 2012
<b>Inspector(s):</b> L Heppler, P. Brinton	<b>Time:</b> 11:30 AM
<b>Other Participants:</b> Zeb Kenyon and others	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 06-22-2014 **Bond Amount:** \$3,873,446 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. This site was last inspected as a large mine 03/10/2011, by Leslie Heppler.

**Inspection Summary:** Access to site was limited by gate. A few older bone yards were noted on site. No erosional problems were noted. Mines and dumps and BC South have been reclaimed. The Barneys pit has been reclaimed, and most of the haul roads. Attached photographs document area.

Attached photographs document area.

**Conclusions and Recommendations:** Barneys Canyon needs to submit Drill Hole abandonment form. OGM to continue annual inspections and monitor the site when in the area.


**Inspector's Signature**

LAH:eb

cc: Ray Gottling – Barneys Canyon Mine

O:\M035-SaltLake\M0350009-BarneysCyn\Inspections\Insp-05092012.doc





Barneys Canyon Pit - reclaimed



Barneys Canyon Pit - reclaimed



Barneys Canyon Dump - reclaimed



Barneys Canyon Pit - reclaimed



South BC South pit and dump - reclaimed



South BC South pit and dump - reclaimed



North BC South reclaimed



Melco Dump - Reclaimed